	8	((("5867009") or ("6166449") or ("6278195")	USPAT	2002/04/19 20:08
		or ("6209672") or ("6188945") or ("5938712")		
		or ("6158822") or ("6321530")).PN.) and		
		engine same (controller ecu) and engine same	ĺ	
		(ecu controller)		
_	75	high near3 torque near3 (drive adj shaft)	USPAT;	2002/04/19 20:24
		and low near3 (speed revolution rpm)	EPO; JPO;	
		•	DERWENT	
_	19	(high near3 torque near3 (drive adj shaft)	USPAT;	2002/04/20 11:38
		and low near3 (speed revolution rpm)) and	EPO; JPO;	
		engine	DERWENT	
_	1	("6278195").PN.	USPAT	2002/04/20 11:11
_	3	(("6278195") or ("6166449") or	USPAT	2002/04/20 11:12
		("5867009")).PN.		
_	0	l	USPAT	2002/04/20 11:13
		("5867009")).PN.) and (low high) near3		
		torque		
-	4	(("6278195") or ("6166449") or ("5867009")	USPAT	2002/04/20 11:12
		or ("5938712")).PN.		
-	1	((("6278195") or ("6166449") or ("5867009")	USPAT	2002/04/20 11:13
	Ì	or ("5938712")).PN.) and (low high) near3		
		torque		
-	7159	(high near3 torque) same (high near3 (speed	USPAT;	2002/04/20 11:48
		revolution rpm))	EPO; JPO;	
			DERWENT	
-	2224	((high near3 torque) same (high near3 (speed	USPAT;	2002/04/20 11:49
		revolution rpm))) and engine	EPO; JPO;	
			DERWENT	
-	2871	(high near1 torque) near3 (high near1 (speed	USPAT;	2002/04/20 11:52
		revolution rpm))	EPO; JPO;	
			DERWENT	0000/04/00 17 55
-	923	(high adj2 torque) near3 (high adj2 (speed	USPAT;	2002/04/20 11:56
		revolution rpm))	EPO; JPO;	
			DERWENT	0000/04/00 15 55
-	235	((high adj2 torque) near3 (high adj2 (speed	USPAT;	2002/04/20 11:56
	1	revolution rpm))) and engine	EPO; JPO;	
			DERWENT	

- 98 (("5657257") or ("5808881") or ("5673286")	2002/04/19 17:31
or ("5835527") or ("5920590") or ("5995538") or ("6175586") or ("6198262") or ("5535238") or ("5686881") or ("6000829") or ("6068601") or ("6193711") or ("6226316") or ("6226316") or ("4378530") or ("5565807") or ("5640069") or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("6175586") or ("6198262") or ("5535238") or ("5686881") or ("6000829") or ("6068601") or ("6193711") or ("6226316") or ("6226316") or ("4378530") or ("5565807") or ("5640069") or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("5686881") or ("6000829") or ("6068601") or ("6193711") or ("6226316") or ("6226316") or ("4378530") or ("5565807") or ("5640069") or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	:
or ("6193711") or ("6226316") or ("6226316") or ("4378530") or ("5565807") or ("5640069") or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("4378530") or ("5565807") or ("5640069") or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("5757626") or ("5768702") or ("5946086") or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("5961617") or ("6088255") or ("6100643") or ("4296296") or ("4823640") or ("5199904")	
or ("4296296") or ("4823640") or ("5199904")	
or ("5329758") or ("5332979") or ("5381540")	
or ("5446322") or ("5493707") or ("5539477")	
or ("5612639") or ("5619204") or ("5631921")	
or ("5654655") or ("5691603") or ("5699001")	
or ("5770955") or ("5784091") or ("5808460")	
or ("5886586") or ("5978318") or ("6029074")	
or ("6088806") or ("6144595") or ("6144445")	
or ("6211984") or ("6211984") or ("4369409")	
or ("4506502") or ("4538095") or ("4559476")	
or ("4786140") or ("4798950") or ("4800339")	
or ("RE32901") or ("4920309") or ("4943764")	
or ("4970414") or ("5013980") or ("5019996")	
or ("5020391") or ("5250775") or ("5300895")	
or ("5355077") or ("5364316") or ("5396298")	
or ("5399916") or ("5422593") or ("5426347")	
or ("5491457") or ("5559393") or ("5576655")	
or ("5585792") or ("5585962") or ("5587672")	
or ("5619403") or ("5621279") or ("5700089")	
or ("5704210") or ("5719898") or ("5751164")	
or ("5767844") or ("5828717") or ("5835552")	
or ("5850156") or ("5862458") or ("5909586")	
or ("5923103") or ("5959849") or ("5963583")	
or ("5973540")).PN.	2002/04/19 17:33
- 6 290/40c and electric adj motor and ecu and USPAT; engine EPO; JPO;	2002/04/19 17:33
engine EPO; JPO; DERWENT	
	2002/04/19 17:33
- 34 180/65.2.ccls. and electric adj motor and USPAT; ecu and engine EPO; JPO;	2002,01,13 17.33
DERWENT	
- 6 290/40c.ccls. and electric adj motor and ecu USPAT;	2002/04/19 17:33
and engine EPO; JPO;	2002, 01, 13 11100
DERWENT	
- 16 pattern same shaft and determ\$10 near3 unit USPAT;	2002/04/19 19:35
and ecu and engine EPO; JPO;	2002, 02, 22 20 02
DERWENT	
- 238 controller and determ\$10 near3 unit and ecu USPAT;	2002/04/19 20:17
and engine EPO; JPO;	
DERWENT	
- 8 (("5495127") or ("5469816") or ("5371412") USPAT	2002/04/19 19:56
or ("5786640") or ("5867009") or ("6278195")	
or ("6173569") or ("6166449")).PN.	
- 8 (("5867009") or ("6166449") or ("6278195") USPAT	2002/04/19 19:57
or ("6209672") or ("6188945") or ("5938712")	
or ("6158822") or ("6321530")).PN.	
- 4 ((("5867009") or ("6166449") or ("6278195") USPAT	2002/04/19 20:01
or ("6209672") or ("6188945") or ("5938712")	
or ("6158822") or ("6321530")).PN.) and high	
same torque and low same torque	
- 2 ((("5867009") or ("6166449") or ("6278195") USPAT	2002/04/19 20:06
or ("6209672") or ("6188945") or ("5938712")	
or ("6158822") or ("6321530")).PN.) and	
differ\$10 near3 torque	2000/04/22 22 22
- 7 ((("5867009") or ("6166449") or ("6278195") USPAT	2002/04/19 20:08
or ("6209672") or ("6188945") or ("5938712")	
or ("6158822") or ("6321530")).PN.) and	
motor same (controller ecu) and engine same	
(ecu controller)	

- 820	"5657257"	USPAT;	2002/04/19 17:31
	"5808881"	EPO; JPO;	
	"5673286"	DERWENT	
	"5563907"		
	"5574747"		
	"5730139" "5835527"		
	"5920590"		
	"5995538"		
	"6175586"		
	"6198262"		
	"5535238"		
	"5686881" "6000829"		
	"6068601"		
	"6193711"		
	"6226316"		
	"6226316"		
	"4378530"		
	"5565807" "5640069"	:	
	"5757626"		
	"5768702"		
	"5946086"		
	"5961617"		
	"6088255"		
	"6100643" "4296296"		
	"4823640"		
	"5199904"		
1	"5268649"		
	"5299226"		
	"5313850" "5329758"		
	"5332979"		
	"5381540"		
1	"5446322"		
	"5493707"		
	"5539477"		
	"5612639" "5619204"		
	"5631921"		
	"5654655"		
	"5691603"		
	"5699001"		
	"5770955"		
	"5784091" "5808460"		
	"5886586"		
	"5978318"		
	"6029074"		
	"6088806"		
	"6144595" "6144445"		
	"6211984"		1
	"6211984"		
	"4369409"		
	"4506502"		
	"4538095" "4559476"		
	"4786140"		
	"4798950"		
	"4800339"		
	RE32901		
	"4920309"		
	"4943764" "4970414"		
	"5013980"		
	"5019996"		
	"5020391"		
	"5250775"		
	"5300895"		
Search History	1 2 5 5 5 7 7 1 4 2 0 7 0 2 2 9 4 : 55 PM Page 2		
C:\APPS\EAST\Works	pada မြန်နှိုင်တို့ ကြို့ ကြို့ (wsp		
	"5399916"		
i l	1	•	1

* 37 h 1	Hits	Search Text	DB	Time stamp
L Number	7		USPAT; EPO; JPO;	2002/04/19 17:32
-	6	322/\$.ccls. and electric adj motor and ecu and engine and controller	DERWENT USPAT; EPO; JPO;	2002/04/19 17:24
-	46	180/\$.ccls. and electric adj motor and ecu and engine and controller	DERWENT USPAT; EPO; JPO; DERWENT	2002/04/19 17:25
-	16	318/\$.ccls. and electric adj motor and ecu and engine and controller	USPAT; EPO; JPO; DERWENT	2002/04/19 17:26
-	39	701/\$.ccls. and electric adj motor and ecu and engine and controller	USPAT; EPO; JPO; DERWENT	2002/04/19 19:01
_	0	toshifume near2 takaoka	USPAT; EPO; JPO; DERWENT	2002/04/19 17:26
-	25	toshifumi near2 takaoka	USPAT; EPO; JPO; DERWENT	2002/04/19 17:32